


*FIG. 1*



+

2/12




FIG. 2A




FIG. 3




FIG. 4

+

+

3/12




FIG. 5




FIG. 6








FIG. 7

+



4/12



5/12



6/12



7/12

EFFECT OF CABLE CURVATURE ON CABLE POSITION, 5 FT. EXACT DEPTH




FIG. 14




FIG. 15

8/12




FIG. 16




FIG. 17



9/12




FIG. 18




FIG. 19

10/12




FIG.20




FIG.21

DEPTH MEASUREMENT ERRORS NEAR CABLE BEND, 5 FT. CABLE DEPTH




FIG. 22

DEPTH MEASUREMENT ERRORS NEAR CABLE BEND, 5 FT. CABLE DEPTH




FIG. 23

12/12

CABLE DEPTH FROM 2-POINT HEIGHT MEASUREMENTS, 5 FT. DEPTH




FIG.24

DEPTH ERROR DUE TO A FLUX MEASUREMENT ERROR OF 2%




FIG.25